

## CASE STUDY

During a site clean-up a manager found and was preparing to throw out ten Store-Safe site boxes in poor condition. The business owner suggested contacting Store-Safe for options.

The boxes were brought to Trafalgar's Sydney manufacturing facility for assessment and repair. One box was identified as pre-1994 from the 7-digit Sydney phone number.

All ten boxes were restored for a fraction of the replacement cost and returned to the customer to be returned to service on building sites, keeping valuable tools safe for many years to come.



## SITE BOX REFURBISHMENT



Before: Ten site boxes in need of repair



Image shows pre-1994 Store-Safe plate with 7-digit Sydney phone number

## THE DELIVERY

Each site box was assessed for restoration needs and the client was contacted with a quote.

New lids, castors, locks and gas struct installed.

In this case the customer has elected to complete the restoration by repainting the site boxes themselves.

## PRODUCT

Site Box S120

Site Box S200

## PROJECT SIZE

1200 mm

2000 mm

## OPTIONAL EXTRAS

Castors

Lifting Lugs

Bilock System